



Photograph 1) View of the culvert extending under Collins-Gifford Valley Road. Area 19 extends between the culvert and Woodward Lske.



Photograph 2) View of the rocky stream channel that comprises the majority of Area 19.



Photograph 3) View of Area 19, as it reaches the vegetated wetlands located along the fringe of Woodward Lake.



Photograph 4) View of Area 18 and the vegetated wetland area that abuts the stream channel that flows through it.



Photograph 5) View of another small patch of vegetated wetland that abuts the stream channel in Area 18.



Photograph 6) View of the stream channel that flows through Area 18. This segment of the stream does not have vegetated wetland that abuts it.



Photograph 7) View of Area 18 as it meets the scrub-shrub dominated wetland community that is found along the fringe of Woodward Lake.



Photograph 8) View of Area 17. Vegetated wetlands abut both sides of the stream channel.



Photograph 9) Another view of Area 17. Vegetated wetlands abut both sides of the stream channel.



Photograph 10) View of Area 17, as observed from Collins-Gifford Valley Road. Vegetated wetlands extend along both sides of the stream from the road to the edge of Woodward lake.