


Photo 1: State Hwy 30 at Giff's Auto Center
EXISTING CONDITION

Distance to fence: 430 Feet

SARATOGA
ASSOCIATES



Photograph Information
Date: November 14, 2025
Time: 11:17 AM
Focal Length: 52 mm
Photo Location: 43° 11' 44.0988" N 74° 11' 44.8548" W



Figure 1

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 1: State Hwy 30 at Giff's Auto Center
SIMULATED CONDITION WITH LANDSCAPE MITIGATION - YEAR 1 GROWTH

Distance to fence: 430 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:17 AM
Focal Length: 52 mm
Photo Location: 43° 11' 44.0988" N 74° 11' 44.8548" W



Figure 2

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 1: State Hwy 30 at Giff's Auto Center
SIMULATED CONDITION WITH LANDSCAPE MITIGATION - YEAR 5-7 GROWTH

Distance to fence: 430 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:17 AM
Focal Length: 52 mm
Photo Location: 43° 11' 44.0988" N 74° 11' 44.8548" W



Figure 3

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 2: State Hwy 30 south of Giff's Auto Center
EXISTING CONDITION

Distance to fence: 550 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:40 AM
Focal Length: 50 mm
Photo Location: 43°11'42.8"N 74°11'45.5"W



Figure 4

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 2: State Hwy 30 south of Giff's Auto Center
EXISTING CONDITION

Distance to fence: 550 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:40 AM
Focal Length: 50 mm
Photo Location: 43°11'42.8"N 74°11'45.5"W



Figure 5

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY




Photo 2: State Hwy 30 south of Giff's Auto Center
EXISTING CONDITION

Distance to fence: 550 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:40 AM
Focal Length: 50 mm
Photo Location: 43°11'42.8"N 74°11'45.5"W



Figure 6

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 3: State Hwy 30 near North Country Metals
EXISTING CONDITION

Distance to fence: 320 Feet

SARATOGA
ASSOCIATES

Photograph Information
Date: November 14, 2025
Time: 11:29 AM
Focal Length: 50 mm
Photo Location: 43° 11' 51.7829" N 74° 11' 42.4593" W



Figure 7

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 3: State Hwy 30 near North Country Metals
SIMULATED CONDITION WITH LANDSCAPE MITIGATION - YEAR 1 GROWTH

Distance to fence: 320 Feet

**SARATOGA
ASSOCIATES**

Photograph Information
 Date: November 14, 2025
 Time: 11:29 AM
 Focal Length: 50 mm
 Photo Location: 43° 11' 51.7829" N 74° 11' 42.4593" W



Figure 8

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY



Photo 3: State Hwy 30 near North Country Metals
SIMULATED CONDITION WITH LANDSCAPE MITIGATION - YEAR 5-7 GROWTH

Distance to fence: 320 Feet

**SARATOGA
ASSOCIATES**

Photograph Information
 Date: November 14, 2025
 Time: 11:29 AM
 Focal Length: 50 mm
 Photo Location: 43° 11' 51.7829" N 74° 11' 42.4593" W



Figure 9

SACANDAGA BESS
1030 State Hwy 30
Northampton, NY